



Industry Engineering

Description Hydraulic components and systems

Building Factory

Flooring Application

RCR Flooring Products Limited

RCR Products

Permaban Signature AR



Date of Completion 2016

Technical Notes

Repair of 8.97m of damaged floor joint in industrial floor.

For full case study, please visit: <http://permaban.com/case-studies/signature-ar-kpm-comes-back-for-more>

“We’re very pleased with the floor repair using Permaban Signature AR. Forklifts can cross the joint easily; the floor looks professional and we know it will stay that way.”

— Ray Wilson, Maintenance Manager, Kawasaki Precision Machinery

